

Inspection Photos
Location Name: Kowach 1-9
Location ID: 312913



Photo 1. Overview of location taken facing southwest.

Inspection Photos
Location Name: Kowach 1-9
Location ID: 312913



Photo 2. Gauge hatch open on produced water tank.



Photo 3. Stained soil in tank battery.