

Inspection Photos

**Location Name: MARALEX RESOURCES INC DOME ALBERTSON-69S98W /32SENW,
Location ID: 312498**



Photo #1089 from entrance to location



Photo # 1090 Multiple places with debris on location.

Inspection Photos

Location Name: MARALEX RESOURCES INC DOME ALBERTSON-69S98W /32SENW,

Location ID: 312498



Photo #1091 Multiple places with debris on location.