

Inspection Photos

Loc#427776

Operator: Grizzly

Inspection Number: 692402119

Inspection Date: 4/22/2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of location to Northwest.

April 22, 2020



Photo#2:
Erosion concerns.



Photo#3:
Erosion concerns.

April 22, 2020



Photo#4:
Erosion concerns.



Photo#5:
Erosion concerns.

April 22, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly ALs GGU Federal Loc#427776



Photo#6:
Areas of Cheat grass establishment.

April 22, 2020



Photo#7:
View over water feature to Northwest.



Photo#8:
View over rocky slope to Southeast.

April 22, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly ALs GGU Federal Loc#427776