

Inspection Photos

Loc#417608

Operator: Grizzly

Inspection Number: 692402118

Inspection Date: 4/22/2020



Photo#1:

Overview of location where SO berm has been removed and wattles installed down gradient.

April 22,2020




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly Stranahan Loc#335440



Photo#2:
Stormwater repairs.



Photo#3:
Stormwater repairs.

April 22,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly Stranahan Loc#335440