

Inspection Photos

4/28/2020

Operator: BAYSWATER EXPLORATION &
PRODUCTION LLC - 10261

Location ID: 315536

Rio Blanco County, CO

Aaron Trujillo
NW Reclamation Specialist
COGCC

Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 315536



Photo 1: Photo taken from the north end of the Location, facing east. Photos 1-3 provide an overview of the reclamation from east, to south to west.



Photo 2: See comments under photo 1.

Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 315536



Photo 3: See comments under photo 1.



Photo 4: Photo taken from the access road, facing west. Photo shows reclamation in process.

Inspection Photos

Operator Name: BAYSWATER EXPLORATION & PRODUCTION LLC - 10261

Location ID: 315536



Photo 5: Photo taken from the access road. Photo shows road base/rock material on the access road; material may not be conducive to reclamation. If it is determined that the rock material is hindering vegetative establishment, a corrective action will be applied for it's removal per 1004.a



Photo 6: Photo taken from the Location. Photo shows a remnant Halogeton plant from the 2019 growing season. Photo shows what appears to be Halogeton plant germination occurring. Due to the early timing of the growing season, and difficulty distinguishing young halogeton plants from other weedy species (e.g. Russian Thistle), a follow up inspection will need to be conducted when vegetation growth has progressed to allow accurate identification, and to determine compliance with 1004.e