

Final Reclamation Inspection

April 30, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 327533

Inspection Document #: 697501441

Weld County, CO

NESE Section 6 T3N R64W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: MCKENNEY #6-3
Location ID: 327533



Photo 1. Photo taken from the northern well location, facing North. Photo illustrates Operator has failed to remove equipment.

Inspection Photos
Location Name: MCKENNEY #6-3
Location ID: 327533



Photo 2. Photo taken from the northern well location, facing East. Photo illustrates the Operator attempted final reclamation activities with the evidence of drill rows; however, there is little establishment desirable plant species. The location consists mostly of weedy, annual vegetation (Kochia) with bare soil. In addition to Kochia, there is a high density of cheatgrass observed in other areas.

Inspection Photos
Location Name: MCKENNEY #6-3
Location ID: 327533



Photo 3. Photo taken from the northern well location, facing West. See comments under Photo 2.

Inspection Photos
Location Name: MCKENNEY #6-3
Location ID: 327533



Photo 4. Photo taken from the central well location, facing East. See comments under Photo 2.

Inspection Photos
Location Name: MCKENNEY #6-3
Location ID: 327533



Photo 5. Photo taken from the central well location, facing North. See comments under Photo 2.

Inspection Photos
Location Name: MCKENNEY #6-3
Location ID: 327533



Photo 6. Photo taken from the associated offsite tank battery, facing West. See comments under Photo 2.

Inspection Photos
Location Name: MCKENNEY #6-3
Location ID: 327533



Photo 7. Photo taken from the associated offsite tank battery, facing East. See comments under Photo 2.

Inspection Photos
Location Name: MCKENNEY #6-3
Location ID: 327533



Photo 8. Reference photo taken north of the well location, facing North.