

Renegade Oil & Gas Company LLC, Champlin 126 Amoco G 1
005-06721

Inspection #688307750

4/30/2020

Annual Bradenhead Test Inspection



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

**RENEGADE
OIL & GAS COMPANY**
(303) 680-4725

Champlin 126 Amoco G #1
SW SE Sec 29, T4S, R62W
Arapahoe County, Colorado

In Case of Emergency Call 911

Colorado Oil and Gas Conservation Commission
39.6678, -104.34805, 5456.0ft, 218°
04/30/2020 08:56:41 AM



Colorado Oil and Gas Conservation Commission
39.66781, -104.34805, 5456.0ft, 204°
04/30/2020 08:56:49 AM

FORM
17
Rev
5/99

State of Colorado
Oil and Gas Conservation Commission
1120 Lincoln Street, Suite 801, Denver, Colorado 80202 Phone: (303) 864-2100 Fax: (303) 864-2105

OGCC RECEIPT

BRADENHEAD TEST REPORT

Step 1. Record all tubing and casing pressures as found. Step 2. Sample flow. If intermediate or surface casing pressure is 20 psi or greater, allow 1 min. Step 3. Conduct Bradenhead test. Step 4. Conduct intermediate casing test. Step 5. Record system to 60.4 within 3 days and to OGCC within 10 days. Include surface casing pressure if not previously submitted or if surface configuration has changed since prior program. Attach gas and liquid analysis if sampled.

Document Number:
402382861

1. OGCC Operator Number: 74185
2. Name of Operator: RENEGADE OIL & GAS COMPANY LLC
3. BLM Lease No:
4. API Number: 05-005-08721-00
5. Multiple completion? ☐ Yes ☒ No
6. Well Name: CHAMPLIN 125 AMOCO G
7. Location (OrrGr, Sec, Twp, Rng, Meridian): SWSE 25 4S 62W 8
8. County: ARAPAHOE
9. Field Name: DRAGON
10. Minerals: ☒ Fee ☐ State ☐ Federal ☐ Indian

11. Date of Test: 04/30/2020
12. Well Status: ☒ Flowing ☐ Shut In ☐ Gas Lift
☐ Pumping ☐ Injection
☐ Cyclic/Intermittent
☐ Plunger Lift
13. Number of Casing Strings: ☒ Two ☐ Three ☐ Liner?

Record all pressures as found
Tubing: ☒ Fm: DSND
Prod Csg: ☒ Intermediate Csg: ☐ Surf. Csg: ☐

14. EXISTING PRESSURES

Buried valve? ☐ Yes ☒ No
Confirmed open? ☒ Yes ☐ No
With gauges monitoring production, intermediate casing and tubing pressures, open surface casing (bradenhead) valve (if no pressures, monitor only the production casing and tubing pressures.) Record pressures at five minute intervals. Define characteristics of flow in "Bradenhead Flow" column using letter designations below:
O = No Flow; C = Continuous; D = Down to 0; V = Vapor
H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas

BRADENHEAD TEST

Elapsed Time (Min Sec)	Fm. Tubing	Prod Csg PSIG	Intermediate Csg PSIG	Bradenhead Flow
00:00				
05:00				
10:00				
15:00				
20:00				
25:00				
30:00				

Instantaneous Bradenhead PSIG at end of test: > 0

BRADENHEAD SAMPLE TAKEN?
☐ Yes ☒ No
Character of Bradenhead fluid: ☐ Clear ☐ Fresh
☐ Sulfur ☐ Salty ☐ Black
Other (describe):
Sample cylinder number:

INTERMEDIATE CASING TEST

Buried valve? ☐ Yes ☒ No
Confirmed open? ☐ Yes ☒ No
With gauges monitoring production, intermediate casing and tubing pressures, open the intermediate casing valve. Record pressures at five minute intervals. Characterize flow in "Intermediate Flow" column using letter designations below:
O = No Flow; C = Continuous; D = Down to 0; V = Vapor
H = Water H2O; M = Mud; W = Whisper; S = Surge; G = Gas

Elapsed Time (Min Sec)	Fm. Tubing	Prod Csg PSIG	Intermediate Csg PSIG	Bradenhead Flow
00:00				
05:00				
10:00				
15:00				
20:00				
25:00				
30:00				

INTERMEDIATE SAMPLE TAKEN?
☐ Yes ☒ No
Character of intermediate fluid: ☐ Clear ☐ Fresh
☐ Sulfur ☐ Salty ☐ Black
Other (describe):
Sample cylinder number:

Colorado Oil and Gas Conservation Commission

39.59154, -104.35444, 5584.0ft, 84°

04/30/2020 03:23:31 PM

429/2020 Doc: [402382861]

Comments: Bradstreet test performed on the Colorado 125, Article 121 as required per provision of COGCC rule in test at well located in Adams County. Initial Bradstreet test performed on 04/30/2020.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Test Performed By: Matthew Ingle Title: Field Engineer Phone: (800) 947-3848

Signed: Edward Ingle Title: Manager/Owner Date: _____

Witnessed By: [Signature] Title: Field Inspector Agency: COGCC

Colorado Oil and Gas Conservation Commission
39.5916, -104.35436, 5603.7ft, 82°
04/30/2020 03:23:40 PM