

Inspection Photos

Loc#335438

Operator: Grizzly

Inspection Number: 692402117

Inspection Date: 4/22/2020





Photo#1:
Overview of upper & lower levels of Location

April 22,2020



Photo#2:

Area West side of pad where sediment is migrating into interim. Insert small scale tunneling at well head.


April 22,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#3:



Inspection Photos: Grizzly Silt Valley Loc#335438



Photo#4:
Erosion developing in NE Interim area of lower pad.

Photo#5:

April 22,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly Silt Valley Loc#335438