

Inspection Photos

Loc#335339

Operator: Grizzly

Inspection Number: 692402120

Inspection Date: 4/22/2020





Photo#1:
Overview of Location.

April 22,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Grizzly GGU Loc#311596



Photo#2:
View of pad area that needs to be stabilized.

April 22,2020



Photo#3:

Currently there is Rat Hole (?) that has cover bent up / open to ingress..

April 22,2020



Photos #4 & 5:
BMPs installed.

April 22, 2020