

**CAERUS PICEANCE LLC
CHEVRON-66S96W 7SWNW
Garden Gulch 7 Rockslide
Location # 335881**



View of Garden Gulch 7 from Garden Gulch 4



CAERUS PICEANCE LLC
CHEVRON-66S96W 7SWNW
Garden Gulch 7 Rockslide
Location # 335881



**CAERUS PICEANCE LLC
CHEVRON-66S96W 7SWNW
Garden Gulch 7 Rockslide
Location # 335881**



Damaged Chemical Container at wells.



Spill from damaged chemical container.

**CAERUS PICEANCE LLC
CHEVRON-66S96W 7SWNW
Garden Gulch 7 Rockslide
Location # 335881**



CAERUS PICEANCE LLC
CHEVRON-66S96W 7SWNW
Garden Gulch 7 Rockslide
Location # 335881



**CAERUS PICEANCE LLC
CHEVRON-66S96W 7SWNW
Garden Gulch 7 Rockslide
Location # 335881**



CAERUS PICEANCE LLC
CHEVRON-66S96W 7SWNW
Garden Gulch 7 Rockslide
Location # 335881



Fallen rocks at back separators.



CAERUS PICEANCE LLC
CHEVRON-66S96W 7SWNW
Garden Gulch 7 Rockslide
Location # 335881



Damaged gathering line.



CAERUS PICEANCE LLC
CHEVRON-66S96W 7SWNW
Garden Gulch 7 Rockslide
Location # 335881



**CAERUS PICEANCE LLC
CHEVRON-66S96W 7SWNW
Garden Gulch 7 Rockslide
Location # 335881**



Damage to separators.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources