

**Inspection Photos**  
**Location Name: Gaspar 11-1**  
**Location ID:320468**



**Photo 1 WH sign**



**Photo 2 dead weeds around well head**

**Inspection Photos**  
**Location Name: Gaspar 11-1**  
**Location ID:320468**




**Photo 3 dead weeds around meter house**



**Photo 4 dead weeds around Hoz sep burner.**

**Inspection Photos**  
**Location Name: Gaspar 11-1**  
**Location ID:320468**



**Photo 5 meter test date of 2-1-19 missing annual inspection**

**Photo 6 Dead weeds around TNK BTRY**

**Inspection Photos**  
**Location Name: Gaspar 11-1**  
**Location ID:320468**



Colorado Oil and Gas Conservation Commission  
39.99937, -104.95714, 1534.3m  
May 4, 2020 11:23:57

**Photo 7 hole in bird netting**



Colorado Oil and Gas Conservation Commission  
39.99938, -104.95708, 1534.3m  
May 4, 2020 11:24:19

**Photo 8 Dead weeds around TNK BTRY**