


**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 317497**




**Photo 1 – Sign at County Road**



**Photo 2 – Pumping Unit, weeds and Unused Pipe**



**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 317497**



**Photo 3 – Pumping Unit, weeds, Drum not labeled**



**Photo 4 – Stained Soil inside the Engine House**





**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 317497**



**Photo 5 – Heater Treater, weeds, Wildlife screen missing**



**Photo 6 – Stained Soil at Heater Treater**



**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 317497**



**Photo 7 – Tank Berm Integrity, Compromised, Weeds**




**Photo 8 – Tank Berm Integrity, Compromised, Weeds**



**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 317497**



**Photo 9 – Stained Soil inside the Treater shed**



**Photo 10 – Unused pipe at Manifold Area, East of Pit**

**Inspection Photos**  
**Location Name: Henderson #1**  
**Location ID: 317497**



**Photo 11 – Pit – Gaps in Mesh, and Weeds**