

Inspection Photos
Location Name: Behring 1
Location ID: 317496



Photo 1 – Sign at County Road



Photo 2 – Tank Battery



Inspection Photos
Location Name: Behring 1
Location ID: 317496



Photo 3 – Pumping Unit, weeds, stained soil



Photo 4 – Stained Soil at Pumping Unit

Inspection Photos
Location Name: Behring 1
Location ID: 317496



Photo 5 – Pumping Unit, weeds, stained soil



Photo 6 – Stained Soil at Pumping Unit

Inspection Photos
Location Name: Behring 1
Location ID: 317496



Photo 7 – Stained soil at Pumping Unit




Photo 8 – Stained Soil at Pumping Unit

Inspection Photos
Location Name: Behring 1
Location ID: 317496



Photo 9 – Weeds at Heater Treater



Photo 10 – Tanks – Rust, Berm Integrity Compromised, Weeds

Inspection Photos
Location Name: Behring 1
Location ID: 317496




Photo 11 – Flowlines not properly abandoned, Weeds at Pit



Photo 12 – Weeds at Pit Area