

FORM  
5A

Rev  
06/12

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203 Phone: (303) 894-2100 Fax: (303) 894-2109



DE ET OE ES

Document Number:

402351034

Date Received:

03/25/2020

COMPLETED INTERVAL REPORT

The completed interval Report, Form 5A, shall be submitted within thirty (30) days of completing a formation (successful or not), when a formation is temporarily abandoned or permanently abandoned, for a recompletion, reperforation or restimulation, or when a formation is commingled. Fill out a section for each formation. Attach as many pages as required to fully describe the work. List in order of completion.

1. OGCC Operator Number: 100322  
2. Name of Operator: NOBLE ENERGY INC  
3. Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070  
4. Contact Name: Craig Richardson  
Phone: (303) 228-4232  
Fax:  
Email: Denverregulatory@nblenergy.com

5. API Number 05-123-24484-00  
6. County: WELD  
7. Well Name: ALM USX E  
Well Number: 11-13  
8. Location: QtrQtr: SWSW Section: 11 Township: 6N Range: 65W Meridian: 6  
9. Field Name: WATTENBERG Field Code: 90750

Completed Interval

FORMATION: CODELL Status: TEMPORARILY ABANDONED Treatment Type:  
Treatment Date: End Date: Date of First Production this formation: 04/05/2007  
Perforations Top: 7142 Bottom: 7154 No. Holes: 48 Hole size: 42/100  
Provide a brief summary of the formation treatment: Open Hole: ☐  
This formation is commingled with another formation: ☐ Yes ☒ No  
Total fluid used in treatment (bbl): Max pressure during treatment (psi):  
Total gas used in treatment (mcf): Fluid density at initial fracture (lbs/gal):  
Type of gas used in treatment: Min frac gradient (psi/ft):  
Total acid used in treatment (bbl): Number of staged intervals:  
Recycled water used in treatment (bbl): Flowback volume recovered (bbl):  
Fresh water used in treatment (bbl): Disposition method for flowback:  
Total proppant used (lbs): Rule 805 green completion techniques were utilized: ☐  
Reason why green completion not utilized:

Fracture stimulations must be reported on FracFocus.org

Test Information:

Date: Hours: Bbl oil: Mcf Gas: Bbl H2O:  
Calculated 24 hour rate: Bbl oil: Mcf Gas: Bbl H2O: GOR:  
Test Method: Casing PSI: Tubing PSI: Choke Size:  
Gas Disposition: Gas Type: Btu Gas: API Gravity Oil:  
Tubing Size: Tubing Setting Depth: Tbg setting date: Packer Depth:  
Reason for Non-Production: Surface Equipment removed on 1/17/2019.  
Date formation Abandoned: 01/17/2019 Squeeze: ☐ Yes ☐ No If yes, number of sacks cmt  
\*\* Bridge Plug Depth: \*\* Sacks cement on top: \*\* Wireline and Cement Job Summary must be attached.

Comment:

This well is TA because surface equipment was removed due to LTSI. There are no plugs downhole.

I hereby certify all statements made in this form are, to the best of my knowledge, true, correct, and complete.

Signed: \_\_\_\_\_ Print Name: Julie Webb

Title: Sr. Regulatory Analyst Date: 3/25/2020 Email julie.webb@nblenergy.com  
:

### **Attachment Check List**

**Att Doc Num**      **Name**

402351034	FORM 5A SUBMITTED
-----------	-------------------

Total Attach: 1 Files

### **General Comments**

**User Group**      **Comment**

**Comment Date**

		Stamp Upon Approval
--	--	------------------------

Total: 0 comment(s)