

Inspection Photos

Loc#334940

Operator: Caerus

Inspection Number: 692402127

Inspection Date: 4/23/20





Photo#1:
Overviews of Location to West and North.

April 24 ,2020



Photo#2:
SW retention area at base of common slope.



Photo#3:
Sinkhole off ditch leading from pad.

April 24 ,2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Benzel Loc#334944