

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /8NENE

Location ID: 334269



Photo #1114 from entrance to location



Photo #0690 from inspection #699800681 conducted on 3/3/20.

Inspection Photos

Location Name: MARALEX RESOURCES INC SOUTH SHALE RIDGE-68S98W /8NENE

Location ID: 334269




Photo #1115 Tank label weathered and not legible.

