

Final Reclamation Inspection

May 5, 2020

Operator: NOBLE ENERGY INC - #100322

Location ID: 322664

Inspection Document #: 697501469

Weld County, CO

NENE Section 16 T4N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: WILLMAN-H #41-16
Location ID: 322664



Photo 1. Photo taken north of the well location, facing South. Photo illustrates a TA well which is part of a variance waiving the requirements for a MIT. Photo also illustrates much of the low growing vegetation is that of Kochia- see Photo 3.

Inspection Photos
Location Name: WILLMAN-H #41-16
Location ID: 322664



Photo 2. Photo taken of the TA well, facing South. Photo illustrates the TA well appears to be locked out and tagged per the variance.

Inspection Photos
Location Name: WILLMAN-H #41-16
Location ID: 322664



Photo 3. Close-up photo taken from around the well. Photo illustrates Kochia rosettes that will have to be managed in the future.

Inspection Photos
Location Name: WILLMAN-H #41-16
Location ID: 322664



Photo 4. Photo taken from the associated offsite tank battery, facing East. Photo illustrates Operator has performed some of the final reclamation requirements (i.e., remove gravel). However, there was very little germination of desirable species; therefore, it does not appear the tank battery has been seeded. Also, there is an active remediation.

Inspection Photos
Location Name: WILLMAN-H #41-16
Location ID: 322664



Photo 5. Photo taken from the associated offsite tank battery, facing North. Photo illustrates vehicle traffic. Operator should consider temporarily fencing off the area as this is not stabilized and to help promote successful vegetation establishment to stabilize the area.