

Inspection Photos
Operator: BP America
API#: 067-07546
Date: 5/5/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Cut-slope appears to be seeded and straw mulch observed on slope. Dense houndstongue weeds present.



Photo 3. View of the southern project area from the southeastern edge facing westward. Grasses appear to be progressing here with straw mulch present and seedlings observed.



Photos 4/5. View of houndstongue and musk thistles observed within the project area, respectively from left and right. Approximately 500 houndstongue and 50 musk thistles present.



Photo 6. View of reference area open grass field, comprised of intermediate wheatgrass.