

Inspection Photos

API: 055-06256

Operator: PETROGLYPH OPERATING CO

Inspection Date: 5/4/2020



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 055-06256 | Date: 5/4/2020

Inspection Photos



Photo 1. Facing east along the main access road just past the location. There is erosion along the road at Lat/Long:37.54165,-104.82527.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06256 | Date: 5/4/2020

Inspection Photos



Photo 2. Additional BMP's along the road just past the location to prevent erosion along the road side.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06256 | Date: 5/4/2020

Inspection Photos



Photo 3. Facing north toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06256 | Date: 5/4/2020

Inspection Photos



Photo 4. Facing northeast at the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06256 | Date: 5/4/2020

Inspection Photos



Photo 5. Facing east at south side of the location. There was mostly vegetative debris from last years growth. There was minimal growth from this year in this area.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06256 | Date: 5/4/2020

Inspection Photos



Photo 6. View of ground cover. There was minimal new growth observed. Some of the vegetation from last years growth appears to be Sand dropseed and Cheat grass.



Photo 7. Some of last years vegetation appears to be Cheat grass.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos



Photo 8. Facing west toward the location. There is minimal growth of vegetation from this year. This area needs additional reseeding.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06256 | Date: 5/4/2020

Inspection Photos



Photo 9. Facing southwest toward the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06256 | Date: 5/4/2020

Inspection Photos



Photo 10. Facing northwest toward the surrounding undisturbed reference area. Vegetation consists of Pinion Juniper woodland and Blue grama, Western wheat grassland.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 055-06256 | Date: 5/4/2020