

Inspection Photos

Loc#334658

Operator: Caerus

Inspection Number: 692402161

Inspection Date: 4/29/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

April 29, 2020



Photo#2:
Tank with holes at base.

April 29, 2020