

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

05/07/2020

Submitted Date:

05/07/2020

Document Number:

699301664

FIELD INSPECTION FORM

Loc ID 318769 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421643	WELL	SI	07/01/2019	OW	123-32989	PALYO 21-11	SI
421647	WELL	TA	03/08/2016	OW	123-32990	PALYO 3-11	TA
421649	WELL	SI	07/01/2019	OW	123-32992	PALYO 22-11	SI
421655	WELL	SI	07/01/2019	OW	123-32996	PALYO 28-11	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:	adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	adequate x 4		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	IGNITOR/COMBUSTOR		
Comment:	barbless wire		
Corrective Action:		Date:	
Type	SEPARATOR		
Comment:	Shares fencing with ignitor/combustor		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	barbless wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	AG fence		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 8		

Comment: automation		Date:
Corrective Action:		Date:
Type: Pig Station	# 1	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 3	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 4	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Bradenhead	# 4	
Comment: all are exposed at surface		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate
Other (Content)	
Other (Capacity) 210 bbl	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: shares containment with crude oil tanks					
Corrective Action:		Date:			
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:		Date:			

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 421643 Type: WELL API Number: 123-32989 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI since 7-1-2019

Corrective Action: _____

Date: _____

Facility ID: 421647 Type: WELL API Number: 123-32990 Status: TA Insp. Status: TA

Idle Well

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: _____

Comment: TA since 3-8-2016

Corrective Action: _____

Date: _____

Facility ID: 421649 Type: WELL API Number: 123-32992 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI since 7-1-2019

Corrective Action: _____

Date: _____

Facility ID: 421655 Type: WELL API Number: 123-32996 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: SI since 7-1-2019

Corrective Action: _____

Date: _____

COGCC Comments

Comment

User

Date

COGCC Inspection Report Summary
On Thursday 5/7/2020 at approximately 1300 hrs. I, Inspector Robbie Revas,
Conducted an on-site inspection at a Kerr McGee location:

Palyo 22-11 at Location #318769 in
Weld County Colorado.
While there, I observed SI/TA multi well well site and tank battery.
the Palyo 22-11, 21-11 and 28-11 have been SI since 7-1-2019.
The Palyo 3-11 has been TA ince 3-8-2016, Form 04 (TA) Doc # 402063899 was submitted
on 6-4-2019 and is approved.
During this inspection no compliance issues were observed:
See attached photos.
Location is dry, weather is clear.
No follow up on this site inspection needs to be conducted to ensure the
Compliance issues have been corrected to comply with COGCC rules.
Continuing education COGCC Inspection Report Summary.
This is a summary of inspection report.

revasr

05/07/2020

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699301665	location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5144961
699301666	TB pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5144962