

**Inspection Photos**  
**Location Name: LARAMIE ENERGY LLC BCU /14L Pad**  
**Location ID: 312704**



**Photo #1136 from entrance to location**



**Photo #1138 1000 gallon tank not properly labeled.**

## Inspection Photos

Location Name: LARAMIE ENERGY LLC BCU /14L Pad

Location ID: 312704



**Photo #1137 Unused equipment by separator.**