

Inspection Photos

Loc#324383

Operator: Caerus

Inspection Number: 692402165

Inspection Date: 4/30/20





Photo#1:
Overview of Location.

April 30, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus MCU Loc#324383



Photo#2:
Unmarked Anchor.



Photo#3:
Pieces of Debris.

April 30, 2020




Photo#4:
Interim area.

April 30, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#5:
Stormwater areas of concern.

Caerus MCU Loc#324383