

Inspection Photos

Loc#324936

Operator: Caerus

Inspection Number: 692402166

Inspection Date: 4/30/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

April 30, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Pitman Loc#334936



Photo#2:
Soil, debris, gravel pushed into interim areas



Photo#3:
Soil, debris, gravel pushed into interim areas.

April 30, 2020



Photo#4:
Stormwater areas of concern



Photo#5:
Stormwater areas of concern.

April 30, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Pitman Loc#334936



Photo#1:
Interim area.

April 30, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Pitman Loc#334936