


Ward & Son Alfred, Kloefkorn 1
121-09045


Inspection #688307803

5/4/2020

Reinspection



Colorado Oil and Gas Conservation Commission
39.82634, -103.34346, 4865.5ft, 142°
05/04/2020 12:19:31 PM



Stained soil in
treater shed at
flowline.

Colorado Oil and Gas Conservation Commission
39.82643, -103.3436, 5055.8ft, 127°
05/04/2020 12:21:16 PM



Subsidence at
produced water
tanks.

Colorado Oil and Gas Conservation Commission
39.82604, -103.34338, 4849.1ft, 114°
05/04/2020 12:21:47 PM



Recent vac
truck tracks.

Colorado Oil and Gas Conservation Commission
39.82602, -103.34334, 4849.1ft, 308°
05/04/2020 12:22:03 PM



Colorado Oil and Gas Conservation Commission
39.82592, -103.34331, 4842.5ft, 295°
05/04/2020 12:24:17 PM



Colorado Oil and Gas Conservation Commission

39.82557, -103.34332, 4845.8ft, 321°

05/04/2020 12:23:32 PM



Colorado Oil and Gas Conservation Commission

39.82579, -103.3433, 4852.4ft, 215°

05/04/2020 12:22:45 PM



Colorado Oil and Gas Conservation Commission
39.82566, -103.3433, 4855.6ft, 243°
05/04/2020 12:23:07 PM



Colorado Oil and Gas Conservation Commission
39.82602, -103.34335, 4849.1ft, 247°
05/04/2020 12:22:07 PM



Pit berms
eroding into
field.

Colorado Oil and Gas Conservation Commission
39.82556, -103.34331, 4852.4ft, 11°
05/04/2020 12:23:29 PM



Pit berms
eroding
into
pasture.

Colorado Oil and Gas Conservation Commission
39.82556, -103.34331, 4852.4ft, 199°
05/04/2020 12:23:24 PM