

Inspection Photos  
Operator: BP America  
API#: 067-08745  
Date: 5/8/2020



Photo 1. View of the northern well pad from the southwestern corner facing center.





Photo 2. View of erosional channel approximately 2 feet wide and deep forming within the northwestern corner of the project area.





Photo 3. View of the central fill slope from the southwestern corner facing eastward. Revegetation is progressing with rubber rabbitbrush and grasses such as western wheatgrass.





Photo 4. View of the northern fill slope from the northwestern corner facing eastward.





Photo 5. View of reference area comprised of mixed pinyon and juniper woodland, with sagebrush and mixed herbaceous understory (ie: blue grama, Navajo tea)