

Final Reclamation Inspection

May 7, 2020

Operator: PDC ENERGY INC - 69175

Location ID: 309789

Inspection Document #: 697501485

Weld County, CO

NENW Section 31 T5N R63W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: R & R FARMS /21-31
Location ID: 309789



Photo 1. Photo taken from the associated offsite tank battery location, facing East. Photo illustrates the Operator has removed the meter shed but has failed to perform final reclamation activities.

Inspection Photos
Location Name: R & R FARMS /21-31
Location ID: 309789



Photo 2. Photo taken north of the well location/well location access road, facing South. Photo illustrates the crop field is currently fallow.