

**Tiffany Gathering  
Photographic Log  
BP America Production Co.**



Photo 1: Overview of release area, 4/8/2020.




Photo 2: Point of release, 4/8/2020.





Photo 3: White residue on vegetation within wet area in field, 4/8/2020.



Photo 4: SS01 collected from area adjacent to the point of release, 4/8/2020.





Photo 5: SS02 collected from wet area in field, 4/8/2020.



Photo 6: SS03 collected from wet area in wetland, adjacent to WS02, 4/8/2020.





Photo 7: SS04 collected as a background sample from hillside adjacent to and upgradient of the point of release, 4/8/2020.



Photo 8: WS01 collected from the point of release, 4/8/2020.





Photo 9: WS02 collected from the wet area in wetland, adjacent to SS03, 4/8/2020.




Photo 10: WS03 collected as a potential point of compliance sample downgradient of wet area in wetland, 4/8/2020.





Photo 11: SS05 collected upgradient of the release area in wetland, 4/24/2020.



Photo 12: SS06 collected as a potential point of compliance sample downgradient of wet area in wetland, adjacent to WS03, 4/24/2020.





Photo 13: SS07 collected near the point of release at the base of the bell hole excavation, 4/24/2020.



Photo 14: Excavation of ruptured pipeline, 4/24/2020.