

# Inspection Photos

5/07/2020

Operator: CAERUS PICEANCE LLC # 10456

Location ID: 335856

Garfield County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

**Inspection Photos**  
**Operator Name: CAERUS PICEANCE LLC # 10456**  
**Location ID: 335856**



**Photo 1:** Photo taken from the north end of the Location, facing southeast. Photo shows Location remains flat, and has not been contoured in accordance with Rule 1004.a. Records indicate this is due to safety concerns regarding the stability of the adjacent landslide area.



**Photo 2:** Photo taken from the north end of the Location, facing southwest. See comments under photo 1.



**Inspection Photos**  
**Operator Name: CAERUS PICEANCE LLC # 10456**  
**Location ID: 335856**



**Photo 3:** Photo taken from south end of the Location, facing north. Photo shows what appears to be a sediment trap/pond or pit. BMP does not appear to be in proper functioning condition, or constructed in such a manner to collect runoff from the pad. Feature will either need to be repaired in accordance with good engineering practices, or removed/reclaimed if no longer in use or needed.



**Photo 4:** Photo taken from the north end of the trap/pond/pit observed in photo 3, facing southeast. Photo shows no inlet at BMP to catch runoff from the pad, or outlet for proper discharge.

Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 335856



**Photo 5:** 2017 COGIS aerial imagery. Photo shows location of trap/pond/pit observed on the south end of the Location.



Inspection Photos  
Operator Name: CAERUS PICEANCE LLC # 10456  
Location ID: 335856



**Photo 6:** Photo taken from access road, northwest of the pad, facing southeast. Photo shows vegetative establishment on the fill slope of the Location.

