

Inspection Photos  
Location Name: Powers 11-27  
Location ID: 332396



Photo 1 WH sign




Photo 2 WH

**Inspection Photos**  
**Location Name: Powers 11-27**  
**Location ID: 332396**



**Photo 3 TB signs**



**Photo 4 TB**

**Inspection Photos**  
**Location Name: Powers 11-27**  
**Location ID: 332396**



**Photo 5 stained soil under valve on crude oil tank**



**Photo 6 Horiz. Heated Sep., ECD and gas meter runs**



**Location ID: 332396**

[illegible]

**Photo 7 card inside of meter house**


[illegible]

**Photo 8 card inside of meter house**

**Inspection Photos**  
**Location Name: Powers 11-27**  
**Location ID: 332396**



**Photo 9 stained concrete inside of meter house**



**Photo 10 possible valve leak inside of meter house**