



Graphic Controls

Test witnessed

CHART NO. MC MP-100-1H

Cobec 3/18/20

METER

42 PSI

CHART PUT ON

1:00

M

TAKEN OFF

2:05 PM

M

LOCATION

Exc 4AW consolidation line

REMARKS

Flowline Repair

James Strang

03.18.2020 13:11