

Inspection Photos

5/13/2020

Operator: EAGLE OPERATING INC - 26155

Location ID: 397838

Rio Blanco County, CO

Aaron Trujillo

NW Reclamation Specialist

COGCC

Inspection Photos
Operator Name: EAGLE OPERATING INC - 26155
Location ID: 397838



Photo 1: Photo taken from the well facing southeast. Photo shows oil and gas associated utility equipment remaining on the Location.



Photo 2: Photo taken from the south end of the Location, facing southeast. Photo shows oil and gas associated utility equipment on, and leading to, the Location. Equipment requires removal in accordance with 1004 rules.

Inspection Photos
Operator Name: EAGLE OPERATING INC - 26155
Location ID: 397838



Photo 3: Photo shows exposed wire that had cut at the utility pole.

