

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

05/07/2020

Submitted Date:

05/08/2020

Document Number:

689501035**FIELD INSPECTION FORM**Loc ID 318298 Inspector Name: Oakman, Kari On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections
Evans, Jacob		jacob.evans@nblenergy.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
441401	SPILL OR RELEASE	CL	03/27/2015		-	SPILL/RELEASE POINT	EI

General Comment:

This is an environmental inspection of Remediation Project No. 9116 which remains open in the COGCC database. COGCC Environmental staff found no evidence of remaining impacts on location.

Photo attached to document location at time of inspection.

Any corrective actions from previous inspections that have not been addressed are still applicable.

Environmental**Spills/Releases:**

Type of Spill: _____

Estimated Spill Volume: _____

Comment: Remediation Project No. 9116 remains open in the COGCC database. The COGCC has no documentation of the progress of this remediation since 6/3/2015. COGCC Environmental staff found no evidence of remaining impacts on location.

Corrective Action: Submit a Supplemental Form 27 providing an update on progress of the remediation project at this location.

Date: 07/07/2020

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

Lat

Long

DWR Receipt Num: _____

Owner Name: _____

GPS : _____

Field Parameters:

Sample Location: _____

Comment: _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402393681	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5145762
689501036	Field photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5145754