

## Inspection Photos

Location Name: MARALEX RESOURCES INC LATHAM-68S99W /18SEnw

Location ID: 312472



Photo #1188 from NE corner of location



Photo #1189 Multiple places with debris on location.

## Inspection Photos

Location Name: MARALEX RESOURCES INC LATHAM-68S99W /18SENW

Location ID: 312472



**Photo #1190 Multiple places with debris on location.**