





40.19739, -107.48005, 7975.8ft, 61°  
05/14/2020 11:24:24 AM



40.19752, -107.48, 8013.5ft, 232°  
05/14/2020 11:22:36 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 3. Propane tanks.**

**Government Trinity NCT 1 API: 05-103-09217**  
**Inspection: 700401485**



40.19811, -107.47998, 8026.2ft, 92°  
05/14/2020 11:20:17 AM



40.19728, -107.47995, 8003 9ft, 325°  
05/14/2020 11:24:40 AM



40.19752, -107.47992, 8029.6ft, 59°  
05/14/2020 11:26:26 AM



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

**Photo 6. Stained gravel at pump jack.**

**Government Trinity NCT 1 API: 05-103-09217**  
**Inspection: 700401485**





40.19759, -107.47996, 8022.6ft, 131°  
05/14/2020 11:26:38 AM