

Investment Equipment LLC, Kincheloe 1  
121-09205

Inspection #688307860

5/13/2020

Reinspection




**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources



Colorado Oil and Gas Conservation Commission  
39.80272, -103.06133, 4573.5ft, 91°  
05/13/2020 11:20:35 AM



Valve still  
leaking.

Colorado Oil and Gas Conservation Commission  
39.80274, -103.0613, 4557.1ft, 106°  
05/13/2020 11:20:46 AM





Animal hole in  
tank berm.

Colorado Oil and Gas Conservation Commission  
39.80114, -103.06104, 4560.4ft, 68°  
05/13/2020 11:25:49 AM



Unused  
equipment.

Colorado Oil and Gas Conservation Commission  
39.80123, -103.06104, 4566.9ft, 309°  
05/13/2020 11:27:05 AM





Waste piles on  
north side of pit.

Colorado Oil and Gas Conservation Commission  
39.80133, -103.06195, 4553.8ft, 98°  
05/13/2020 11:23:42 AM



Oily waste pile  
on NE corner of  
pit.

Colorado Oil and Gas Conservation Commission  
39.80125, -103.06153, 4563.6ft, 272°  
05/13/2020 11:22:38 AM





Unused pipe.

Colorado Oil and Gas Conservation Commission  
39.80134, -103.06193, 4550.5ft, 246°  
05/13/2020 11:23:37 AM





Waste piles on  
south side of  
pit.

Colorado Oil and Gas Conservation Commission  
39.80091, -103.06197, 4573.5ft, 75°  
05/13/2020 11:28:48 AM