

Inspection Photos
Location Name: Federal Ostrich 29-8-6
Location ID: 330807




Photo 1 – Wellhead, Unmarked Riser and Trash

Photo 2 – Wellhead Sign

Inspection Photos
Location Name: Federal Ostrich 29-8-6
Location ID: 330807



Photo 3 – Unmarked Deadman Anchor

Photo 4 – Unmarked Deadman Anchor

Inspection Photos
Location Name: Federal Ostrich 29-8-6
Location ID: 330807



Photo 5 – Unmarked Riser south of Wellhead