

# *Inspection Photos*

*Loc#334960*

*Operator: Caerus*

*Inspection Number: 692402199*

*Inspection Date: 5/15/20*



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#1:  
Overview of Location.

May 15, 2020



Photo#2:  
Tank 1.



Photo#3:  
Drip at valve, Tank 1.

May 15, 2020





Photo#4:  
Subsidence NW of Rose Ranch Wellhead.

May 15, 2020



Photo#5:  
Subsidence NW of Rose Ranch Wellhead.

Caerus Rose Ranch Loc#334960





Photo#6:

Interim area; ruderal/debris weeds and Thistle and Houndstongue rosettes.

May 15, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Rose Ranch Loc#334960