

Inspection Photos
Location Name: Green 1-7 Facility (South)
Location ID: 429231



Photo 1 – Tank Battery

Photo 2 – Pit

Inspection Photos
Location Name: Green 1-7 Facility (South)
Location ID: 429231



Photo 3 – South side of Pit - Gaps

Photo 4 – NE Corner Gaps

Inspection Photos
Location Name: Green 1-7 Facility (South)
Location ID: 429231



Photo 5 – Unmarked 1” Riser SE of Pit

Photo 6 – Unmarked 2” Risers SE of Crude Oil Tanks