



Form Information

Form Name: **Compliance Follow Up Form**
Submitter Name: Cole Nichols (colen@horizonenvservices.com)
Submission Date: Apr 21, 2020 1:20:49 PM MDT
Server Receive Date: Apr 21, 2020 1:23:58 PM MDT
Reference Number: 20200421-18140302368
Location: 91 S Skylane Dr, Durango, CO 81303, USA
Apr 21, 2020 1:20:27 PM MDT [[View Map](#)]

Information

Name colen@horizonenvservices.com
Date Apr 20, 2020
Well Name UTE GAS UNIT AC 2
API Number 50670881200
Select State Colorado
Work type COGCC Inspection AR
Action Complete Other

Photo of first corrective action completed



Completed work description Corrective Action 1

location sign

Photo of second corrective action completed



Completed work description of corrective action 2

treated musk thistle

Photo of third corrective action completed



Completed work description of corrective action 3
 Photo of fourth corrective action completed

treated musk thistle



Completed work description
 Completed work description of corrective action 4
 Completed work description
 Summary of all work completed

treated roadsides
 treated noxious weeds
 treated noxious weeds
 previous treatment dates 6/15/16, 7/21/17, 6/11/18,
 5/2/19