



## Form Information

**Form Name:** Compliance Follow Up Form  
**Submitter Name:** Kenneth Canterbury (kenneth.canterbury@crossfire-llc.com)  
**Submission Date:** May 12, 2020 3:06:30 PM MDT  
**Server Receive Date:** May 13, 2020 1:00:12 PM MDT  
**Reference Number:** 20200512-18141986280  
**Location:** 399 Co Rd 315, Ignacio, CO 81137, USA  
May 12, 2020 3:00:26 PM MDT [ [View Map](#) ]

## Information

**Name** kenneth.canterbury@crossfire-llc.com  
**Date** May 12, 2020  
**Well Name** WAYT, BUFORD GAS UNIT A 1  
**API Number** 50670687500  
**Select State** Colorado  
**Work type** COGCC Inspection AR  
**Action Complete** Compliance Inspection Actions  
Clean up Operator Debris  
Replaced/Repaired Well Sign

Photo of first corrective action completed



Completed work description Corrective Action 1

Compliance

Photo of second corrective action completed



Completed work description of corrective action 2  
Photo of third corrective action completed



New well sign

Completed work description of corrective action 3  
Photo of fourth corrective action completed



Cleaned up trash

Completed work description  
Completed work description of corrective action 4  
Additional photos



Picked up old well sign  
Picked up trash

Summary of all work completed

Compliance, picked up trash, and installed new well sign