

Inspection Photos

Loc#419862

Operator: Terra

Inspection Number: 692402190

Inspection Date: 5/14/20





Photo#1:
View of Interim at West, or fill side of reclamation.

May 14, 2020




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Mead Loc#419862



Photo#2:
Interim at East side, of Location.




Photo#3:
Interim at East side, of Location.

May 14, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Mead Loc#419862



Photo#4:
Weeds blown into equipment areas.



Photo#5:
Weedy soil/debris pile.

May 14, 2020




COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos: Terra Mead Loc#419862



Photo#6:
Weed filled BMPs.



Photo#7:
Weed filled BMPs.

May 14, 2020



Photo#8:
Irrigated area of Interim Rec.



Photo#9:
Irrigated area of Interim Rec.

May 14, 2020