

# Final Reclamation and Stormwater Inspection

May 18, 2020

Operator: WHITING OIL & GAS CORPORATION- #96155

Location ID: 318632

Inspection Document #: 697501522

Weld County, CO

SWNW Section 7 T10N R58W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources

Inspection Photos  
Location Name: NELSON RANCHES #2  
Location ID: 318632



**Photo 1.** Photo taken from the eastern well location, facing North. Photo illustrates Operator has failed to perform final reclamation activities. There is no indication that final reclamation activities commenced. The well location consists mostly of annual, weedy cover of Kochia and bare ground.



Inspection Photos  
Location Name: NELSON RANCHES #2  
Location ID: 318632



**Photo 2.** Close up photo taken from the well location illustrating bare ground and kochia rosettes.



Inspection Photos  
Location Name: NELSON RANCHES #2  
Location ID: 318632



**Photo 3.** Photo taken from the southeastern well location. Operator has failed to remove all equipment.



Inspection Photos  
Location Name: NELSON RANCHES #2  
Location ID: 318632



**Photo 4.** Photo taken from the southwestern well location, facing West. See comments under Photo 1.



Inspection Photos  
Location Name: NELSON RANCHES #2  
Location ID: 318632



**Photo 5.** Photo taken from the southwestern well location, facing North. See comments under Photo 1.

Inspection Photos  
Location Name: NELSON RANCHES #2  
Location ID: 318632



**Photo 6.** Photo taken from the northwestern guy line anchor, facing North. See comments under Photo 1.



Inspection Photos  
Location Name: NELSON RANCHES #2  
Location ID: 318632



**Photo 7.** Reference photo taken west of the well location, facing West. Photo illustrates vegetative growth comprising mostly of blue grama with sand dropseed, prairie sandreed, and sand sagebrush.