

Inspection Photos
Location Name: UPR 43 PAN AM B#1
Location ID: 317685




Photo 1 Casing pressure Opsi



Photo 2 Braden head pressure Opsi

Inspection Photos
Location Name: UPR 43 PAN AM B#1
Location ID: 317685



Colorado Oil and Gas Conservation Commission
40.07845, -104.99194, 1524.7m
May 19, 2020 09:26:51

Photo 3 tubing injection pressure 1250psi



Colorado Oil and Gas Conservation Commission
40.07845, -104.99194, 1525.8m
May 19, 2020 09:27:02

Photo 4 WH