

# *Inspection Photos*

*Loc#433706*

*Operator: Caerus*

*Inspection Number: 692402183*

*Inspection Date: 5/12/20*





Photo#1:  
Overview of Location from entry.

May 12, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Rose K22W Loc#433706



Photo#2:  
Cuttings pile along Cut.

May 12, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



Photo#3:  
Cuttings pile along Cut.

Caerus Rose K22W Loc#433706



Photo#4:  
Cuttings pile along Cut with debris.



Photo#5:  
Stormwater area of concern.

May 12, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Rose K22W Loc#433706



Photo#6:  
Noxious weed rosettes.



Photo#7:  
Noxious weed rosettes.

May 12, 2020



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources

Caerus Rose K22W Loc#433706