

Inspection Photos
Location Name: Martin T. Hart B unit 1
Location ID: 317839



Photo 1 WH sign operator name and emergency # faded.

Photo 2 WH

Inspection Photos
Location Name: Martin T. Hart B unit 1
Location ID: 317839



Photo 3 PU



Photo 4 transformers, meter box and electric panel

Inspection Photos
Location Name: Martin T. Hart B unit 1
Location ID: 317839



Photo 5 TB sign



Photo 6 Diamond placard is torn and not legible

Inspection Photos
Location Name: Martin T. Hart B unit 1
Location ID: 317839



Photo 7 gas meter run



Photo 8 Horizontal Heated Separator