

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

05/15/2020

Submitted Date:

05/15/2020

Document Number:

701000722**FIELD INSPECTION FORM**
 Loc ID 336951 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:                     
**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Beard, Alyssa		regulatory@foundationenergy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280913	WELL	PR	01/21/2006	GW	125-09606	STONE 33-26	PR

**General Comment:**

Routine Inspection

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action	L	Date:	

Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Lease sign by water tank		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Metal sign by water tank		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			
	Date:		

Overall Good: ☒

<b>Spills:</b>				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	PBV FIBERGLASS		40.023400,-102.366580
Comment:	Fiberglass water tank 50% buried on south side of wellhead				
Corrective Action:					Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:		
Corrective Action:		Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	280913	Type:	WELL	API Number:	125-09606	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing. Casing production. Central meter run for (Stone 1-26, 3-26, 4-26, 31-26, 33-26, 41-26, 1-25, 12-25) 1790' NNE at Stone 1-26								
Corrective Action:							Date:		

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date:

Pits: ☒ NO SURFACE INDICATION OF PIT