

Inspection Photos
Operator: BP America
API#: 067-06362
Date: 5/20/2020



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing westward. Revegetation is progressing with grasses such as western wheatgrass, sand dropseed, and smooth brome.



Photo 3. View of the southern project area from the southeastern corner facing westward.



Photo 4/5. View of dense Scotch thistles within the southeastern project area. Thistles were observed scattered throughout the interim reclamation area. Approximately 200 individuals observed.



Photo 6. View of reference area vegetation comprised of pinyon juniper woodland with understory of gambel oak, black sage, muttongrass, and penstemon.