

Inspection Photos

Loc#324019

Operator: Caerus

Inspection Number: 69240201

Inspection Date: 5/15/20



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#1:
Overview of Location.

May 15, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Pitman Loc#324019



Photo#2:
Interim.

May 15, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Caerus Pitman Loc#324019



Photo#3:
Anchor Marker that needs paint.

May 15, 2020



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources



Photo#4:
Anchor Marker that needs paint.

Caerus Pitman Loc#324019



Photo#5:
Staining at back of separator



Photo#6:
Staining at back of separator.

May 15, 2020