

Inspection Photos

Location ID, Name: 327384, CHAMPLIN 203 AMOCO 'A'-63N66W 5SENE



**Photo 1 05-123-14601CHAMPLIN
203 AMOCO 'A'1**



Photo 2 Battery




Photo 3 Production Equipment



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources